



## European Aviation Safety Agency

### Applications & Procurement Services Department

---

**ASI INNOVATION**

Jean-Pierre KOHN  
46, rue de la Pagerie  
51470 Moncetz Longevas  
France

Cologne, 3 August 2010  
EASA D (2010)/FST/JQU/53790

**Subject:** EASA.AP338 - Demonstration of capability for design -  
Supplemental Type Certificate and Repair Design  
**Reference:** EASA Form 81 dated 21/01/2010  
**Attachment:** 1. EASA finding of compliance, Issue 1 (original)

Dear Mr Kohn,

The European Aviation Safety Agency is pleased to enclose herewith the EASA finding of compliance related to the demonstration of capability for design of **ASI INNOVATION**, required by 21A.115(b) and 21A.432B(b) for the issue of a Supplemental Type Certificate and Repair Design.

Henceforth your organisation shall be entitled to perform design activities under applicable European regulations and for the design cases identified in the statement herein enclosed.

Yours sincerely,

A handwritten signature in black ink that reads "Jane Quist". The signature is written in a cursive, flowing style.

Jane Quist  
Administrative Assistant

Cc: Roger Simon, EASA DO Manager

Certificates & Approvals Section  
Tel.: +49 (0)221 89990 6023 · Fax: +49 (0)221 89990 6523 · Email: [approvals@easa.europa.eu](mailto:approvals@easa.europa.eu)

Postal address: Postfach 10 12 53 · D-50452 Cologne, Germany – Visiting address: Ottoplatz, 1 · D-50679 Cologne, Germany  
Tel.: +49 (0)221 8999 0000 · Fax: +49 (0)221 8999 0999 · E-mail: [info@easa.europa.eu](mailto:info@easa.europa.eu) · [www.easa.europa.eu](http://www.easa.europa.eu)

**Procedures demonstrating capability for design**

**EASA finding of compliance – AP338**

**1 Company name and address:**

**ASI Innovation  
46, rue de la Pagerie  
51470 Moncetz Longevas  
France**

**2 Design approval case for which the Company applied for an alternative procedure to DOA:**

<b>Eligibility</b>	
<b>TC, STC or major repair</b>	<b>Description of case</b>
- for STC, as per 21A.112B and GM 21A.112B  - for major repairs, as per 21A.432 B	<b>Products:</b> CS22 –CS23 – CS 25 – CS VLA – CS VLR Repairs to aircraft MTOW less than 5700 kg <b>Changes:</b> group 2 <b>Fields:</b> Avionics and Electrical systems Cabin Interior Secondary Structure
<b>ETSOA</b>	

**3 Reference of Procedures:**

<b>Reference</b>	<b>Title</b>	<b>Issue/Date</b>
ASI-ALT/01/10	Manuel de L'Organisme de Conception, Procédures Alternatives	Edition 1, revision 0, 14/04/2010

**4 Statement of Project Manager having checked the procedures:**

I hereby state technical approval of the procedures referenced above as meeting the requirement of 21A.112B(b) and 21A.432B (b).

Name: Jacques GOURDEAU

Signature: 

Date: 07/07/2010

**5 EASA DO Manager signature:**

Name: Roger SIMON  
EASA DO Manager

Signature: 

Date of issue: 09/07/2010