



ASI INNOVATION



## Liste STC

---

<i>Manufacturer</i>	<i>Aircraft Type</i>	<i>STC Number</i>	<i>Issue Date</i>	<i>STC owner</i>
Cessna	T206H	10035229	07/06/2011	EASA 338 ASI-Innovation
Installation of FLIR MX10				
Cessna	T206H	10036203	19/08/2011	EASA 338 ASI-Innovation
Revision of STC 0002 : location change DVFAR, extension harness MX10				
Cessna	F406	10031373	12/08/2010	EASA 338 ASI-Innovation
Glide relay installation				
Cessna	F406	10032798	01/12/2010	EASA 338 ASI-Innovation
Glide relay installation				
Cessna	F406	10030390	14/06/2010	EASA 338 ASI-Innovation
Repair of wiring SN066				
Cessna	T206H	10031933	23/09/2010	EASA 338 ASI-Innovation
Flir MX10 Mechanical installation provision				
Embraer	EMB120	10030971	19/07/2010	EASA 338 ASI-Innovation
Installation owner id plate EMB120				
Cessna	F406	10033435	19/01/2011	EASA 338 ASI-Innovation
Installation FDR APIBOX iAERO				
Cessna	F406	10032904	07/12/2010	EASA 338 ASI-Innovation
UHF antenna installation and PMR/DMR Mission console Mechanical provision installation				
Cessna	F406	10033966	23/02/2011	EASA 338 ASI-Innovation
UHF antenna installation and PMR/DMR Mission console Mechanical provision installation				
Cessna	F406	10032011	01/10/2010	EASA 338 ASI-Innovation
Installation seat belt Anjou aéronautique on Reims F406 S/N061				
ATR	ATR 42/72	10033040	15/12/2010	EASA 338 ASI-Innovation
Installation cabine interior tissue (AIRLINAIR)				
ATR	ATR 42/72	10033165	21/12/2010	EASA 338 ASI-Innovation
Installation carpet (AIRLINAIR)				
ATR	ATR 42/72	10037289	16/11/2011	EASA 338 ASI-Innovation
Revision affaire 0022 additional information on drawings				
ATR	ATR 42/72	10033366	14/01/2011	EASA 338 ASI-Innovation
Installation rideau commercial et embase en tissu (AIRLINAIR)				
ATR	ATR 42/72	10033369	14/01/2011	EASA 338 ASI-Innovation
Installation rideau anti-fumée - entrée soute arrière (AIRLINAIR)				
ATR	ATR 42/72	10033374	14/01/2011	EASA 338 ASI-Innovation
Installation rideau anti-fumée - entrée soute arrière (AIRLINAIR)				
Cessna	T206H	10033104	17/12/2010	EASA 338 ASI-Innovation
Modifcation console PMR/DMR				
Cessna	T206H	10033934	21/02/2011	EASA 338 ASI-Innovation
Installation external outlets 30 Amp on T206H French customs				
Cessna	T206H	10035549	29/06/2011	EASA 338 ASI-Innovation
Revision affaire ASI-0030 additional floor compartment				
Cessna	F406	10033414	19/01/2011	EASA 338 ASI-Innovation
Repair internal leading edge internal				

Cessna	F406	10034256	21/03/2011	EASA 338 ASI-Innovation
Modification console polmar F406 (computer LNE)				
Cessna	T206H	10034304	24/03/2011	EASA 338 ASI-Innovation
Certification arm MX10 on console PMR DMR				
Cessna	T206H	10036828	10/10/2011	EASA 338 ASI-Innovation
Revision affaire ASI-0034 : additional covers and arm mod MX10				
Cessna	T206H	10033881	16/02/2011	EASA 338 ASI-Innovation
Antenne location change NTX T206				
Cessna	F406	10034560	12/04/2011	EASA 338 ASI-Innovation
Installation UHF antenna				
Cessna	F406	10034420	04/04/2011	EASA 338 ASI-Innovation
Installation compartment PMR/DMR F406 surmar + F406 S/N 61				
Cessna	F406	10035864	22/07/2011	EASA 338 ASI-Innovation
Revision affaire ASI-0037 : additional covers				
Cessna	T206H	10034469	07/04/2011	EASA 338 ASI-Innovation
Installation Motorola systeme Motorola				
Cessna	T206H	10036532	16/09/2011	EASA 338 ASI-Innovation
Revision affaire ASI-0038, additional switches guard affaire ASI-0063				
Cessna	F406	10034417	04/04/2011	EASA 338 ASI-Innovation
Installation system Motorola				
Cessna	F406	10035884	25/07/2011	EASA 338 ASI-Innovation
Revision affaire ASI-0039, additional switches guard affaire ASI-0064				
Cessna	F406	10033640	01/02/2011	EASA 338 ASI-Innovation
Provision installation MX10 on polmar				
Beech	Beech 350	10035241	07/06/2011	EASA 338 ASI-Innovation
Installation oven Beech 350				
Cessna	T206H	10034838	05/05/2011	EASA 338 ASI-Innovation
Installation sabot sur cône arrière T206H				
Cessna	F406	10034883	10/05/2011	EASA 338 ASI-Innovation
Revision FORM0032 for applicability SN 66 (modif CCS)				
Cessna	F406	10035065	23/05/2011	EASA 338 ASI-Innovation
Modification console SAMSARA				
Cessna	F406	10036053	08/08/2011	EASA 338 ASI-Innovation
Removal radiometre F406 66				
Embraer	ERJ 135	10041778	15/10/2012	EASA 338 ASI-Innovation
Modification ERJ 135				
Cessna	T206H	10036388	06/09/2011	EASA 338 ASI-Innovation
Installation sabot sur cône arrière T206H				
Robin	DR400	10037664	16/12/2011	EASA 338 ASI-Innovation
Remplacement seat belt on DR400				
Cessna	C150	10039405	02/05/2012	EASA 338 ASI-Innovation
Radio panel changes Cessna 150				
Tecnam	P2006	10040891	01/08/2012	EASA 338 ASI-Innovation
Installation mission's console				
Cessna	F406	10038613	02/03/2012	EASA 338 ASI-Innovation
Repair lead edge F406				

Cessna	F406	10039486 rev1	14/05/2012	EASA 338 ASI-Innovation
Additional switches to TB (FMS)				
Embraer	ERJ 135	10040999	14/08/2012	EASA 338 ASI-Innovation
Installation oven Emb 135				
Embraer	E190	10038964 rev2	29/03/2012	EASA 338 ASI-Innovation
Replacement floor mat Emb 190				
Embraer	E120	10041603	01/10/2012	EASA 338 ASI-Innovation
Validation fonction PRNAV				
Cessna	F406	10039203	17/04/2012	EASA 338 ASI-Innovation
Remplacement display LNE console Polmar				
ATR	F406	10039124	11/04/2012	EASA 338 ASI-Innovation
Reparation landing gear doors F406				
Embraer	ATR 72	10040033	11/06/2012	EASA 338 ASI-Innovation
Application SB ATR				
Embraer	ERJ 135	10039758	22/05/2012	EASA 338 ASI-Innovation
Inhibition ERASE feature on CVR				
ATR	ATR 42	10042513	05/12/2012	EASA 338 ASI-Innovation
Installation HF 950 ATR42				
Beech	B90	10040616	13/07/2012	EASA 338 ASI-Innovation
installation Radio relay antenna				
Cessna	F406	10040084	12/06/2012	EASA 338 ASI-Innovation
Repair pilot seat				
Embraer	E190	10039835	29/05/2012	EASA 338 ASI-Innovation
Revision remplacement floor mat Emb 190				
Cessna	F406	10040274	21/06/2012	EASA 338 ASI-Innovation
Location change temperature probe				
ATR	ATR 42	10041279	04/09/2012	EASA 338 ASI-Innovation
Installation micro QAR ATR42				
Beech	B90	10042045	05/11/2012	EASA 338 ASI-Innovation
Installation of a video mast B90				
Cessna	T206H	10041817	17/10/2012	EASA 338 ASI-Innovation
Revision affaire ASI-0034				
Cessna	F406	10041850	19/10/2012	EASA 338 ASI-Innovation
Revision affaire ASI-0037				
Cessna	T206H	10041819	17/10/2012	EASA 338 ASI-Innovation
Revision affaire ASI-0038				
Cessna	F406	10041876	22/10/2012	EASA 338 ASI-Innovation
Revision affaire ASI-0039				
Embraer	EMB120	10043486	01/02/2013	EASA 338 ASI-Innovation
Installation relay				
Beech	B350	10043741	21/02/2013	EASA 338 ASI-Innovation
FMS upgrade and PRNAV certification				
Embraer	E190	10040929	03/08/2012	EASA 338 ASI-Innovation
Revision remplacement floor mat Emb 190				
ATR	ATR72	10041573	28/09/2012	EASA 338 ASI-Innovation
New paint certified on ATR72				

Embraer	Emb 145	10041670	05/10/2012	EASA 338 ASI-Innovation
Modification access pannel air conditionning				
Cessna	T206H	10042024	05/11/2012	EASA 338 ASI-Innovation
Modification routing wiring harness compartment				
Beech	B200	10042837	20/12/2012	EASA 338 ASI-Innovation
Remplacement FMS UNS-1Msp by a UNS-1E				
Dasault	F900	10043214	11/01/2013	EASA 338 ASI-Innovation
Remplacement of a transponder				
Embraer	Emb 145	10042811	19/12/2012	EASA 338 ASI-Innovation
Installation curtains/blinds				
ATR	ATR 42	10042513 rev1	22/02/2013	EASA 338 ASI-Innovation
installation HF 950 ATR42				
ATR	ATR72	10043865	01/03/2013	EASA 338 ASI-Innovation
Certification work for a new paint on ATR72				